


Precision Ag Ireland

www.precisionagireland.ie



Connect the CAN connector on cable 62974 to the P2 (CAN) connector on the CFX-750 power cable P/N 77282. Connect power cable 63193 to the power lead on the 62974 cable.

With this option, power off both the display and the EZ-Steer 500 system after you use the system. Failure to do so could result in the vehicle battery power being lost.

Item	Description	Trimble Part Number
1	CFX-750 Display	94100-01
2	CFX-750 power cable	77282
3	CFX-750 basic power cable	67258
4	Coax cable	50449
5	Ag25 GNSS antenna	77038-00
6	EZ-Steer cable with 2-pin power input	62974
7	Direct power cable	63193
8	EZ-Steer Motor	53058-00
9	EZ-Steer motor cable	62257

